

Annexure D

BUILDING SAFETY CERTIFICATE

No 424

Dated :- 01/07/2025

It is certified that the existing building **St. Mary's Academy School** (name of the building or premises) at **Village Akhabandpur, Block Asmoli, District Sambhal, U.P.** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the						
Block	3	-	-	-	-	-

The building is owned/occupied by **St. Mary's Academy School, Village Akhabandpur, Block Asmoli, District Sambhal, U.P.** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **D.R.D.A., Sambhal** (Name of Department/ Govt.) on **30-06-2025** (date of inspection) in the presence of **Rijo Joseph, Manager, St. Mary's Academy School, Village Akhabandpur, Block Asmoli, District Sambhal, U.P** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **01-07-2025** for a period of **Five years** in accordance with rule and subject to compliance of the specific conditions as appended.

1.

Note-This certificate issued on behalf of the documents ,maps provided by the school with the terms and conditions of NBC Certificate issued by joint inspection of AE DRDA and Executive Engineer, Rural Engineering Department , Sambhal, vide Letter No 01 Dated 01-04-2021

Issued on **01-07-2025** at **Sambhal (U.P.)** by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

सहायक अभियन्ता

जिला ग्राम्य विकास अधिकारी

Name : K.K Sharma

Designation : Assistant Engineer

Name & Address of Department/ Office:
D.R.D.A , Sambhal